

Single Survey

survey report on:

Property address	MILL OF DURNO FARM WHITEFORD INVERURIE AB51 5ED
-------------------------	---

Customer	Dr Rogerson & Mrs Rogerson
-----------------	----------------------------

Customer address	MILL OF DURNO FARM WHITEFORD INVERURIE AB51 5ED
-------------------------	---

Prepared by	DM Hall LLP
--------------------	-------------

Date of inspection	25th January 2018
---------------------------	-------------------



PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in the expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

Terms and Conditions

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions. The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:-

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report² will be from information contained in the Report and the generic Mortgage Valuation Report.

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

Terms and Conditions

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

1. Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
2. Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
3. Category 1: No immediate action or repair is needed.

WARNING:

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value, the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The subject property comprises a Detached Two Storey Villa. This includes an immediate area of garden ground, a range of former agricultural type outbuildings, including a large garage/workshop building together with a stone and slate U shaped steading and land extending to 15 acres or thereby.
Accommodation	Ground Floor- Entrance porch, hall, lounge, sitting room, rear hall, dining kitchen, bathroom, office, utility room and shower room. First Floor- Three bedrooms and shower room.
Gross internal floor area (m²)	162 sqm.
Neighbourhood and location	The property is located within a rural locality, close to the small rural hamlet of Whiteford. Although facilities are limited within the immediate vicinity, a wide range of facilities can be found within the nearby town of Inverurie or the city of Aberdeen to the south.
Age	The original dwelling house would have been constructed in excess of 100 years ago. The front porch, and rear wing housing the utility room and shower room would have been later additions.
Weather	Clear and dry following mixed weather.
Chimney stacks	Visually inspected with the aid of binoculars where appropriate. The chimney stacks to the gable elevations, are of solid stone construction, pointed above roof level, capped with stone copings and fireclay pots.

<p>Roofing including roof space</p>	<p>Sloping roofs were visually inspected with the aid of binoculars where appropriate.</p> <p>Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.</p> <p>If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.</p> <p>The main roof area is of pitched timber frame construction, comprising joiner built roof trusses, overlaid with timber sarking, felt, battens and tiles. The ridge is tiled. Access to the roof space was gained by means of a hatch access point to the upper floor bedroom and ground floor rear hall. The loft has been insulated between the ceiling joists within accessible roof void areas. The single storey rear wing, housing the office, rear hall, utility and shower room have a roof of flat timber construction, clad with bituminous felt.</p>
<p>Rainwater fittings</p>	<p>Visually inspected with the aid of binoculars where appropriate.</p> <p>The gutters are of a PVC and cast iron half round design with round PVC and cast iron downpipes.</p>
<p>Main walls</p>	<p>Visually inspected with the aid of binoculars where appropriate.</p> <p>Foundations and concealed parts were not exposed or inspected.</p> <p>The main walls are of mixed construction. The walls are primarily of 600mm solid stone construction, pointed externally while internally strapped and lined with a mixture of lath and plaster and plasterboard. The rear extension, is of 290mm solid concrete blockwork construction, cement rendered externally while internally lined with plasterboard. While the walls to the porch are of 160mm solid brick construction, cement rendered externally while internally lined with plasterboard.</p>
<p>Windows, external doors and joinery</p>	<p>Internal and external doors were opened and closed where keys were available.</p> <p>Random windows were opened and closed where possible.</p> <p>Doors and windows were not forced open.</p> <p>The windows are of a modern double glazed UPVC and timber casement type with timber casement and composite rear and front doors respectively. Soffits and fascias where fitted are formed in timber.</p>

Single Survey

External decorations	Visually inspected. External timbers are painted or stained as necessary.
Conservatories / porches	Visually inspected. There is a porch to the front elevation of blockwork construction, under pitched and tiled roof.
Communal areas	There are no communal areas.
Garages and permanent outbuildings	Visually inspected. There is a small single car garage of timber and timber clad construction, under single skin corrugated asbestos clad roof. To the rear of the dwelling house is a large garage/workshop type structure of portal steel frame construction, with profile metal sheet walls and cement fibre sheet clad roof. There is a small greenhouse and gazebo within the garden area. In addition there is a large U shaped former agricultural type steading building of stone construction, under a mixed slate and profile metal sheet roof.
Outside areas and boundaries	Visually inspected. The subject property incorporates a reasonable amount of immediate garden ground, with access provided by means of a shared access road from the nearest publicly maintained road.
Ceilings	Visually inspected from floor level. Ceilings are formed in a mixture of lath and plaster and plasterboard.
Internal walls	Visually inspected from floor level. Using a moisture meter, walls were randomly tested for dampness where considered appropriate. Internal walls are of mixed timber stud with plaster and plasterboard finish.
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted. The floors are of a mixed suspended timber and composite concreted types. There were no accessible sub-floor areas at the time of inspection.


Single Survey

Internal joinery and kitchen fittings	<p>Built-in cupboards were looked into but no stored items were moved.</p> <p>Kitchen units were visually inspected excluding appliances.</p> <p>Internal joinery finishes are all of timber with painted panelled internal doors and timber skirtings and door facings. Kitchen fittings comprise a range of fitted floor and wall mounted units. A timber stair provides access from the ground to upper floor accommodation.</p>
Chimney breasts and fireplaces	<p>Visually inspected.</p> <p>No testing of the flues or fittings was carried out.</p> <p>There is a LPG gas fire within the lounge and cast iron woodburning stove within the sitting room. Remaining flues appear to have been boarded over internally and they are assumed to have been capped at roof level.</p>
Internal decorations	<p>Visually inspected.</p> <p>Internal walls and ceilings are papered and painted.</p>
Cellars	<p>There are no cellars.</p>
Electricity	<p>Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.</p> <p>The subjects are connected to the mains electrical supply. The meter and consumer unit are located within the rear hall. Visible wiring is in PVC coated cabling incorporating 13 amp socket outlets.</p>
Gas	<p>Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.</p> <p>There is an LPG tank supply which serves the central heating boiler and the gas fire within the lounge.</p>
Water, plumbing, bathroom fittings	<p>Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.</p> <p>No tests whatsoever were carried out to the system or appliances.</p> <p>The property is connected to the mains water supply. The subject property includes a bathroom at ground floor level, with low level</p>

Single Survey

	<p>toilet, wash hand basin, bidet and bath and two shower rooms, one at ground floor level comprising shower tray and power shower with low level toilet and wash hand basin with a separate shower at first floor level comprising low level toilet, wash hand basin, shower tray and power shower over. Visible pipework has been formed in copper and PVC materials.</p>
<p>Heating and hot water</p>	<p>Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.</p> <p>No tests whatsoever were carried out to the system or appliances.</p> <p>The heating within the subject property is provided by means of an LPG fired central heating boiler. The "Worcester Greenstar FS42CDi" boiler serves a series of thermostatically controlled panel radiators within the subject property and also provides the domestic hot water. There is an insulated hot water tank located within the upstairs loft which has an immersion heater fitted.</p>
<p>Drainage</p>	<p>Drainage covers etc. were not lifted.</p> <p>Neither drains nor drainage systems were tested.</p> <p>The subjects are connected to two separate septic tanks, located within the subject property and we understand that the septic tanks are registered with SEPA.</p>
<p>Fire, smoke and burglar alarms</p>	<p>Visually inspected.</p> <p>No tests whatsoever were carried out to the system or appliances.</p> <p>Smoke detectors and carbon monoxide detectors are fitted.</p>
<p>Any additional limits to inspection</p>	<p>At the time of inspection, the subjects were occupied, furnished and all floors covered. My inspection of the roof space was limited due to insulation materials. There were no accessible sub-floor areas. Cupboard accommodation contained personal possessions.</p> <p>An inspection for Japanese Knotweed has not been carried out, and unless otherwise stated, it is assumed that there is no Japanese Knotweed present within the boundaries of the property, or within neighbouring properties.</p>

Sectional Diagram showing elements of a typical house




Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.


Single Survey


2. Condition


This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

 Structural movement	
Repair category	1
Notes	There is evidence of previous movement in the property but within the limitations of my inspection I found no evidence to suggest that the movement appeared serious or that there are any obvious signs of recent movement having occurred.

 Dampness, rot and infestation	
Repair category	1
Notes	Evidence of older woodworm infestation was noted to be affecting timber work within the roof void area. There is evidence of replacement flooring at ground floor levels. Much of the interior fabric appears to have been stripped out and renewed at some point in the past. It is possible that the subject property has previously been treated by specialist contractors, and if possible it would be advantageous to obtain and retain any original guarantees and documentation with the title deeds for future reference purposes. Within the limitations of my inspection I found no evidence of dampness, rot or current timber infestation requiring treatment.

 Chimney stacks	
Repair category	1
Notes	No reportable defects noted. It is however considered prudent to ensure that disused chimneys have been properly capped to prevent against water ingress. A competent building contractor would be able to provide further advice.

 Roofing including roof space	
Repair category	1
Notes	The flat roof to the rear wing is finished in a material with a limited life and although there is no indication of rain penetration, future repair expenditure should be anticipated.

Single Survey



Rainwater fittings

Repair category	1
Notes	No reportable defects noted. Adequacy of rainwater goods however would be tested during periods of heavy rainfall.



Main walls

Repair category	1
Notes	No reportable defects noted.



Windows, external doors and joinery

Repair category	1
Notes	A failed double glazing unit was noted which is to be replaced prior to purchase. It should be understood that others may fail in the short to medium term. A glazier can provide further advice.



External decorations

Repair category	1
Notes	Slight weathering was noted to be affecting the external painted surfaces and regular repainting would be required to maintain an attractive appearance and to prevent deterioration of the building fabric.



Conservatories/porches

Repair category	1
Notes	No reportable defects noted.



Communal areas

Repair category	-
Notes	There are no communal areas.



Garages and permanent outbuildings

Repair category	1
Notes	The outbuildings were noted to be in a fairly wind and water tight condition bearing in mind their age and type. Past movement was noted to be affecting the original steading type outbuilding but this is inkeeping with general age and

Single Survey

	condition.
--	------------



Outside areas and boundaries

Repair category	1
Notes	No significant reportable defects noted. The extent of the subject property should be carefully confirmed by reference to the titles.



Ceilings

Repair category	1
Notes	No reportable defects noted.



Internal walls

Repair category	1
Notes	No reportable defects noted.



Floors including sub-floors

Repair category	1
Notes	No reportable defects noted. Spillage however in kitchens and bathrooms can of course affect the underlying fabric without being obvious on the surface. The flooring in these areas should be checked at close quarters on a regular basis.



Internal joinery and kitchen fittings

Repair category	1
Notes	No reportable defects noted.



Chimney breasts and fireplaces

Repair category	1
Notes	No reportable defects noted. No comment can be made on the condition of flues as these are inaccessible. Appliances, should be checked and tested by an appropriately qualified contractor.

Single Survey



Internal decorations

Repair category	1
Notes	No reportable defects noted.



Cellars

Repair category	-
Notes	There are no cellars.



Electricity

Repair category	2
Notes	We did note that the electrical installation does incorporate an older style rewirable fuse box. This may not satisfy current recommended standards. It is recommended all electrical installations be checked every five years or upon taking occupation to keep up to date with the frequent changes to safety regulations. Further advice would be available from a qualified NICEIC registered contractor.



Gas

Repair category	1
Notes	No reportable defects noted. It is however recommended all gas installations be checked annually and further advice would be available from an appropriately qualified contractor. It is assumed the gas installation was installed in accordance with the regulations in force at the time.



Water, plumbing and bathroom fittings


Repair category	1
Notes	No reportable defects noted.



Heating and hot water

Repair category	1
Notes	No reportable defects noted, but heating systems should be serviced annually to ensure that they run efficiently and safely. There was no evidence of leakage from the hot water systems at the time of inspection.

Single Survey

 Drainage	
Repair category	1
Notes	No reportable defects noted. Covers have not been lifted. I have assumed the drainage system to be in satisfactory working order as there was no evidence of leakage or chokage at the time of inspection.

Single Survey

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	1
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories/porches	1
Communal areas	-
Garages and permanent outbuildings	1
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	-
Electricity	2
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

Single Survey

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground
2. Are there three steps or fewer to a main entrance door of the property?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
3. Is there a lift to the main entrance door of the property?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
4. Are all door openings greater than 750mm?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
5. Is there a toilet on the same level as the living room and kitchen?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
6. Is there a toilet on the same level as a bedroom?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
7. Are all rooms on the same level with no internal steps or stairs?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

It is assumed any necessary Local Authority and other consents would have been sought and obtained in respect of the previous alterations carried out to the subject property and that the appropriate documentation including warrants and completion certificates issued. The extent of garden areas and boundaries, should be carefully confirmed by the conveyancer from the titles. The tenure is assumed to be Absolute Ownership but this should be confirmed.

The subject property may have previously been treated by specialist contractors under guarantee and it would be advantageous if possible to obtain and retain any previous documentation with the title deeds for safe keeping.

Estimated reinstatement cost for insurance purposes

£580,000 (Five Hundred and Eighty Thousand Pounds).

The reinstatement value given is exclusive of outbuildings as their reinstatement cost would be far in excess of their present value. You are therefore advised to contact your own insurers to agree and appropriate replacement cost for the outbuildings.

Valuation and market comments

Market value- £510,000 (Five Hundred and Ten Thousand Pounds).

£70,000 (Seventy Thousand Pounds) of the above sum is attributable to the 15 acres of arable land.

There has been a downturn in the local property market due to regional economic factors however transactions are still taking place.

This is a Replacement Single Survey Report, the original inspection was carried out on 09/09/2015.

Signed	Security Print Code [389819 = 5095] Electronically signed
Report author	IAIN C ROSS
Company name	DM Hall LLP
Address	64 Market Place, Inverurie, AB51 3XN
Date of report	19th February 2018

Mortgage Valuation Report



Property Address

Address MILL OF DURNO FARM WHITEFORD, INVERURIE, AB51 5ED
Seller's Name Dr Rogerson & Mrs Rogerson
Date of Inspection 25th January 2018

Property Details

Property Type House Bungalow Purpose built maisonette Converted maisonette
 Purpose built flat Converted flat Tenement flat Flat over non-residential use
 Other (specify in General Remarks)

Property Style Detached Semi detached Mid terrace End terrace
 Back to back High rise block Low rise block Other (specify in General Remarks)

Does the surveyor believe that the property was built for the public sector, e.g. local authority, military, police? Yes No

Flats/Maisonettes only Floor(s) on which located No. of floors in block Lift provided? Yes No
No. of units in block

Approximate Year of Construction

Tenure

Absolute Ownership Leasehold Ground rent £ Unexpired years

Accommodation

Number of Rooms Living room(s) Bedroom(s) Kitchen(s)
 Bathroom(s) WC(s) Other (Specify in General remarks)

Gross Floor Area (excluding garages and outbuildings) m² (Internal) m² (External)

Residential Element (greater than 40%) Yes No

Garage / Parking / Outbuildings

Single garage Double garage Parking space No garage / garage space / parking space
Available on site? Yes No

Permanent outbuildings:

Large portal steel frame workshop/garage and former agricultural U shaped steading.

Mortgage Valuation Report

Construction

Walls Brick Stone Concrete Timber frame Other (specify in General Remarks)
Roof Tile Slate Asphalt Felt Other (specify in General Remarks)

Special Risks

Has the property suffered structural movement? Yes No

If Yes, is this recent or progressive? Yes No

Is there evidence, history, or reason to anticipate subsidence, heave, landslip or flood in the immediate vicinity? Yes No

If Yes to any of the above, provide details in General Remarks.

Service Connections

Based on visual inspection only. If any services appear to be non-mains, please comment on the type and location of the supply in General Remarks.

Drainage Mains Private None
Electricity Mains Private None
Central Heating Yes Partial None
Water Mains Private None
Gas Mains Private None

Brief description of Central Heating:

LPG fired radiator system.

Site

Apparent legal issues to be verified by the conveyancer. Please provide a brief description in General Remarks.

Rights of way Shared drives / access Garage or other amenities on separate site Shared service connections
 Ill-defined boundaries Agricultural land included with property Other (specify in General Remarks)

Location

Residential suburb Residential within town / city Mixed residential / commercial Mainly commercial
 Commuter village Remote village Isolated rural property Other (specify in General Remarks)

Planning Issues

Has the property been extended / converted / altered? Yes No

If Yes provide details in General Remarks.

Roads

Made up road Unmade road Partly completed new road Pedestrian access only Adopted Unadopted

Mortgage Valuation Report

General Remarks

The property is located within a rural locality, close to the small rural hamlet of Whiteford. Although facilities are limited within the immediate vicinity, a wide range of facilities can be found within the nearby town of Inverurie or the city of Aberdeen to the south.

It is assumed any necessary Local Authority and other consents would have been sought and obtained in respect of the previous alterations carried out to the subject property and that the appropriate documentation including warrants and completion certificates issued. The extent of garden areas and boundaries, should be carefully confirmed with the conveyancer from the titles. The tenure is assumed to be Absolute Ownership but this should be confirmed.

The subject property may have previously been treated by specialist contractors under guarantee and it would be advantageous if possible to obtain and retain any previous documentation with the title deeds for safe keeping.

There is evidence of previous historical movement to the property but within the limitations of my inspection I found no evidence to suggest that any movement appeared serious or that there are obvious signs of recent movement having occurred. The reinstatement value given is exclusive of outbuildings as their reinstatement cost would be far in excess of their present value. You are therefore advised to contact your own insurers to agree and appropriate replacement cost for the outbuildings.

The property includes land extending to approximately 15 acres. We have not measured the land and have assumed this to be correct. Some mortgage lenders place a limit on the amount of ground that may be included in the security. In the event that a lender requires that the ground included with this security be reduced then this may result in a lower valuation being reported to that lender. £70,000 (Seventy Thousand Pounds) of the undernoted sum is attributable to the 15 acres of arable land referred to above.

This is a Replacement Single Survey Report, the original inspection was carried out on 09/09/2015.

Essential Repairs

None noted.

Estimated cost of essential repairs £ Retention recommended? Yes No Amount £

Mortgage Valuation Report

Comment on Mortgageability

Subject to our comments contained within this report and the individual lenders own requirements, we would confirm that the subject property would form suitable security for mortgage purposes.

Valuations

Market value in present condition £ 510,000
Market value on completion of essential repairs £ N/A
Insurance reinstatement value £ 580,000
(to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)
Is a reinspection necessary? Yes No

Buy To Let Cases

What is the reasonable range of monthly rental income for the property assuming a letting on a 6 month Short Assured Tenancy basis? £
Is the property in an area where there is a steady demand for rented accommodation of this type? Yes No

Declaration

Signed Security Print Code [389819 = 5095]
Electronically signed by:-
Surveyor's name IAIN C ROSS
Professional qualifications BSc BLE MRICS
Company name DM Hall LLP
Address 64 Market Place, Inverurie, AB51 3XN
Telephone 01467 624 393
Fax 01467 622 742
Report date 19th February 2018